National Transportation Safety Board NTSB ID: ANC94LA126 Aircraft Registration Number: N9825F FACTUAL REPORT Occurrence Date: 08/31/1994 Most Critical Injury: None **AVIATION** Occurrence Type: Accident Investigated By: NTSB Location/Time Nearest City/Place State Zip Code Local Time Time Zone CAPE SABINE 99752 1830 ADT ΑK Distance From Landing Facility: Direction From Airport: Airport Proximity: On Airport Aircraft Information Summary Aircraft Manufacturer Model/Series Type of Aircraft CESSNA 208 Airplane Sightseeing Flight: No Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On August 31, 1994 at 1830 Alaska daylight time, a wheel equipped Cessna Caravan, C-208, N9825F, registered to and operated by Alaska Island Air, Inc., of Kotzebue, Alaska, dragged a wing during landing at Cape Sabine, Alaska. The Air Taxi Flight, operating under 14 CFR Part 135, departed Kotzebue and the destination was the accident site. A VFR flight plan was filed and visual meteorological conditions prevailed. The pilot and the passenger were not injured and the airplane was substantially damaged.

According to the pilot's statement, he was landing on runway 20 at Cape Sabine and there was a 15 knot crosswind. He applied full flaps on short final and "about 200 feet down the runway I experienced a wind shear and the right wing stalled. There was no indication prior to the wing stalling and the stall warning horn sounded just as the wing stalled due to the shear. The right wing was already low for the crosswind correction, it dropped away and made contact with the runway."

During a telephone conversation with Mike Spisak on September 1, 1994, owner of Alaska Island Air, he stated there was no one else on board the airplane and that this was only a positioning flight. The pilot was supposed to pick up passengers at Cape Sabine. Mr. Spisak stated that the pilot only dragged the wing on the runway, "dinged the right wing," and that the airplane was still flyable.

A statement from Mr. Bruce A. Ream, Cultural Resources Specialist for HartCrouser Inc., who was a passenger on the flight from Kotzebue to Cape Sabine, is included in this report. Mr. Ream states that upon his arrival in Kotzebue, the weather was poor. He discussed various charter operations with Alaska Island Air personnel and was informed that the Cessna Caravan could fly IFR to Point Lay and get past the bad weather.

Alaska Island Air does not have an operations specification authorizing IFR operations in instrument meteorological conditions (IMC) for the Cessna 208 airplane. In accordance with 14 CFR Part 135, an operator is allowed to fly a single engine airplane in IMC from his departure point for 15 minutes provided he will reach visual meteorological conditions (VMC) within 15 minutes and can proceed to the destination under VFR.

The passenger stated that they departed and climbed to 9500 feet, passing through some icing conditions. He said he was holding a handheld GPS unit for the pilot so the pilot could navigate using the GPS.

There is no information in the company manual authorizing the use of GPS as a primary means for navigation. The training manual does not contain any information relating to GPS training.

The passenger's statement continues, "I believe that we descended over the ocean northwest of

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: ANC94LA126

Occurrence Date: 08/31/1994

Occurrence Type: Accident

Narrative (Continued)

Point Lay about 6:15 pm, leveling out at about 750 ft just beneath the clouds. Flew eastward until we saw the coast off the starboard side, circled back and followed the coastline to the southwest staying about one-quarter mile offshore. Distance and direction to Cape Sabin were provided by the GPS."

The passenger stated they departed Kotzebue at 1715 hours and they descended and became VFR at 1815 hours. This does not meet the requirement under 14 CFR Part 135 which allows IFR flight for 15 minutes.

Mr. Ream stated, "the pilot saw the airstrip off to starboard and made a sharp banking turn to the right. The plane began to settle and banked more steeply. I believe that the pilot applied power at this point and attempted to level the plane, but I was watching the ground come up at this point. We were crossing the airstrip at about a 45-degree angle (northwest), heading back out to sea. I felt the plane strike the ground hard and bounce back into the air. My first impression was that the plane was struggling to fly and we would pancake onto the tundra between the airstrip and the bluff. As we passed the bluff the nose pitched down and then up. We began to climb and started to execute a slow turn to the left back toward land. The plane was flying irregularly and I observed that the pilot was fighting the controls. It was at this point that I looked for wing damage, but couldn't see past the radar pod. The pilot stated that we needed to land the plane right away. We completed the turn west of the runway and tried to make an approach from that end, but couldn't get the plane to line up or stay level. My impression is that we were all over the sky at that point. He was having a difficult time working both the engine and flight controls by this time."

"We sank close to the runway, but the plane turned to the right and dipped at the last moment. The pilot powered up to pull out of the approach and drifted southward back toward the camp. I was instructed to get on the controls with the pilot as he was getting tired and running out of strength. We passed by the camp, gained altitude, and made another wide left turn over the water. I held the yoke to the left and tried to help keep the nose level. We came out of the turn northeast of the camp and drifted diagonally southwest toward the airstrip. The pilot instructed me to hold the yoke as far left as I could. Using the engine and prop he maneuvered in low, parallel to the south side of the runway. As soon as we drifted back over the strip we set down hard, using full reverse prop and brakes to stop."

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ANC94LA126

Occurrence Date: 08/31/1994

TACIDAL REPORT	0000	unciio	c Date.	00/31/1994								
AVIATION Occurrence Type: Accident												
Landing Facility/Approach Information												
Airport Name		Airpo	rt ID:	Airport Eleva	tion	Run	way Used	d Runway Length		th	Runv	vay Width
CAPE SABINE Z5				50 Ft	. MSL	20				75		
Runway Surface Type: Gravel												
Runway Surface Condition: Dry												
Type Instrument Approach: NONE												
VFR Approach/Landing: Full Stop												
Aircraft Information												
Aircraft Manufacturer CESSNA			Model/ 208	Series					Serial	Number		
Airworthiness Certificate(s): Normal												
Landing Gear Type: Tricycle												
Homebuilt Aircraft? No Number of Se	eats: 10	(Certified	d Max Gross V	8000 LBS Numbe			er of En	er of Engines: 1			
				Engine Manufacturer: Model/Series: P&W PT6-114					Rated Power:			
- Aircraft Inspection Information												
Type of Last Inspection		Date	ate of Last Inspection Time Sir			ince Last Inspection			Airfrar	ne To	tal Time	
Continuous Airworthiness		08/	08/30/1994					5 Ho	ours			792 Hours
- Emergency Locator Transmitter (ELT) Informat	ion											
ELT Installed? Yes ELT Operated? No ELT					Aided i	n Locating Ad	ccident S	Site?				
Owner/Operator Information												
Registered Aircraft Owner		{	Street A	ddress P.O. BO	X 116	S7						
ALASKA ISLAND AIR, INC.			City							Stat	е	Zip Code
				KOTZEBUE AK 99652 Street Address								99652
Operator of Aircraft Same as Reg'd Aircraft Owner												
Same as Reg'd Aircraft Owner				City						Stat	е	Zip Code
Operator Does Business As: Operator Designator Code:												
- Type of U.S. Certificate(s) Held:												
Air Carrier Operating Certificate(s): On-demand	I Air Taxi											
Operating Certificate:				Operator (Certific	cate:						
Regulation Flight Conducted Under: Part 135: A	Air Taxi & C	omm	uter									
Type of Flight Operation Conducted: Unknown												
	FACT	UAL	REPO	RT - AVIAT	ION							Page 2

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ANC94LA126

Occurrence Date: 08/31/1994

AVIATI	Occurrence Type: Accident											
First Pilot Information												
Name City										ate	Date of Birth	Age
On File On F						ile On F					On File	38
Sex: M Seat Occupied: Left Principal Profession: Civilian Pilot Certificate Number: On										ber: On File		
Certificate(s): Commercial												
Airplane Rating(s): Multi	i-engine Lar	nd; Single-e	ngine Land									
Rotorcraft/Glider/LTA: None												
Instrument Rating(s): Airplane												
Instructor Rating(s): None	Э											
Type Rating/Endorsement for Accident/Incident Aircraft? Current Biennial Flight Review?												
Medical Cert.: Class 2	Medica	l Cert. Status	S: Valid Med	dicalno wa	aivers/lim	1.		Date of	_ast M	ledical E	Exam: 03/25/19	994
	•											
Flight Time Matrix All A/C This Make and Model Single Engine Mult-Engine Airplane Single Engine Mult-Engine					Night	ight Inst		nstrument Simulated		Rotorcraft	Glider	Lighter Than Air
Total Time	3975	110	3375	635	7(00	75		25			
Pilot In Command(PIC)	3500					\dashv						
Instructor						\dashv			_			
Last 90 Days	60					\dashv			_			
Last 30 Days	30					+		+	-			
Last 24 Hours	4				<u> </u> _{To}		a an a Danfa				and Diato N	
Seatbelt Used? Yes	Shou	lder Harness	Used? Yes		10	XICOI	ogy Perfoi	mea?		5	econd Pilot? No)
Flight Plan/Itinerary												
Type of Flight Plan Filed: VF												
								Time Zone				
KOTZEBUE						K	ОТ	ОТZ		1705		ADT
Destination State Airport Identifier												
Same as Accident/Incident Location												
Type of Clearance: None												
Type of Airspace: Airport	Advisory A	rea; Class [)									
Weather Information												
Source of Briefing: No rec	ord of briefi	ng										
Method of Briefing:												
			FACTUAL	REPORT -	- AVIAT	'ION						Page 3

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: ANC94LA126

Occurrence Date: 08/31/1994

Occurrence Type: Accident

	FTYBOR			currence	этурс.	Accidei	IL						
Weather	Information												
WOF ID	Observation Time	Time Zone	WOF	Elevation	on	WOF D	WOF Distance From Accident Site			Direction From Accident Site			
	0000			0 Ft.	MSL			0 NM			0 Deg. Mag.		
Sky/Lowes	t Cloud Condition: Unkr	nown				•	0 Ft.	AGL	Condition of Light: Day				
Lowest Ce	iling: Overcast		12	200 Ft. <i>F</i>	AGL	Visib	ility:	2	SM	Altii	meter:	"Hg	
Temperatu	Temperature: 7 °C Dew Point: °C Wind Direction: 290 Density Altitude:						nsity Altitude:	Ft.					
Wind Spee	ed: 20	Gusts: 2	25		Weather Condtions at Accident Site: Visual Conditions								
Visibility (R	RVR): 0 Ft.	Visibility	(RVV)	0	SM	Intensity of Precipitation: Light							
Restriction	s to Visibility:	·											
Type of Precipitation: Rain													
Accident	Information												
Aircraft Damage: Aircraft Fire: Aircraft Explosion						n							
Classificati	on:												
- Injury Su	mmary Matrix	Fatal	Serious	Minor		None	TOTAL						
First Pi	lot					1		1					
Second	d Pilot												
Studen	t Pilot												
Flight In	nstructor												
Check	Pilot												
Flight E	Engineer												
Cabin A	Attendants												
Other C	Crew												
Passen	igers					1		1					
- TOTAL A	ABOARD -					2		2					
Other G	Ground	0	0		0			0					
- GRAND	TOTAL -	0	0		0	2		2					

TRANSP
National Transportation Safety Board
9 3 3 3
FACTUAL REPORT

FACTŲAL REPÕRT AVĮATION

Occurrence Date: 08/31/1994

Occurrence Type: Accident

istrative	

Investigator-In-Charge (IIC)

GEORGE KOBELNYK

Additional Persons Participating in This Accident/Incident Investigation:

HARLEY HOLT FSDO 01 FAIRBANKS, AK 99701